



P0-7

SIGN:

Danger High Voltage

COMMENT:

Good use of standard Danger trigger word and signage.

RECOMMENDATION:

Mount on outside of fence.



P0-8

SIGN:

Caution Hard Hat Area

COMMENT:

Standardized hard hat signage.

RECOMMENDATION:

None.